

Firmware Release Bulletin

April 11th, 2016

Plus® III Firmware Version: 1.210

Intro: Firmware Version 1.210 addresses some improvements we have made since the launch of firmware version 1.200.

Please report any problems with this beta version to info@pocketwizard.com.

IMPORTANT: This firmware requires PocketWizard Utility version 1.54 or later, available [here](#). When you have installed the latest Utility, connect your Plus III to your computer with a standard Mini-B USB cable. Click "Check For Updates" to begin.

Be sure to update all of your radios to the latest version. Your radios will only operate as expected when all units are using the latest firmware.

Learn More: Visit the [PocketWizard Wiki](#) for more information on using your radios.

Improvements:

- Minor bug fix improving LCD reliability when powering on the Plus III radio.
- Additional support for custom ID channels.