



FlexTT5® for Panasonic Firmware 1.132 Release Notes

Firmware Release Bulletin

August 24th, 2017

ControlTL® FlexTT5® Panasonic Firmware

Firmware Version: 1.132

Intro: Firmware version 1.132 adds compatibility with the Panasonic Lumix GH5.

Please report any problems with this firmware to info@pocketwizard.com.

IMPORTANT: This firmware requires you use PocketWizard Utility version 1.65 or later. It is available [here](#). Upgrade to the latest Utility first, read the "Special Note:" on the next page, and then upgrade your radios' firmware. When updating firmware, be sure to update all of your radios to the latest version. Your radios will only operate as expected when all units are using the latest firmware.

Note: Previously used settings or saved profiles may not be automatically reloaded after installing new firmware. Make sure to record any important settings before loading the firmware because the PocketWizard Utility will perform a factory reset once the installation is complete and your previous settings will be overwritten.

Factory Reset Note: After updating your firmware, always perform a factory reset with the radio: See RESET B [here](#), or simply hold TEST before you power on your radio and continue to hold TEST for about 5 seconds until you see 4 green blinks. While the PocketWizard Utility performs a factory reset automatically when you upgrade the firmware, and has a Factory Reset button on the Update tab, Reset B remains the recommended method after a firmware upgrade.

Learn More:

Visit the [PocketWizard Wiki](#) for more information on using your radios.

New Key Feature:

Compatibility with new Panasonic gear:


The following Panasonic gear is now fully supported in this firmware release:

- **Panasonic Lumix GH5** (Panasonic camera firmware version 1.1)

This gear will work in the ControlTL® system with normal operational considerations. Read more about the [Panasonic FlexTT5](#) on the PocketWizard [Wiki](#).

Special Note for Mac users:

Your Panasonic FlexTT5 radios must be upgraded to Loader Version 1.008 or later to work on a Mac computer. If your Panasonic FlexTT5 does not appear in the PocketWizard Utility on your Mac, then it probably does not have Loader Version 1.008 or later.



The Loader Version upgrade cannot be performed on a Mac computer. It can only be performed on a Windows computer or at the factory.

Please contact [PocketWizard Technical Support](#) for more assistance.