

Firmware Release Bulletin

May 30, 2023

Plus® IIIe Firmware Version: 2.740 and 2.840

Intro: Firmware versions 2.740 and 2.840 address increased compatibility with the Raven from Fusion TLC and improvements with remote camera triggering, as well as specific compatibility for Sony cameras. It also adds a new Rx LR feature for remote camera triggering.

Please report any problems with this firmware version to $\frac{info@pocketwizard.com}{}$.

IMPORTANT: This firmware requires PocketWizard Utility version 2.00 or later, available here. When you have installed the latest Utility, connect your Plus III to your computer with a standard Mini-B USB cable. Click "Check for Updates" to begin.

Be sure to update all of your radios to the latest version. Your radios will only operate as expected when all units are using the latest firmware.

Learn More: Visit the PocketWizard Wiki for more information on using your radios.

Compatibility Updates:

- Radio compatibility: Firmware versions 2.740 and 2.840 enable seamless communication with the most current version of firmware for the Raven from Fusion TLC, as well as all other PocketWizard radios using the most updated E Release firmware.
- Remote camera compatibility updates: Firmware 2.740 allows the Plus IIIe's sync port to work with either mono or stereo sync cables. With firmware 2.840, the sync port can only use stereo cables. 2.840 can be used for triggering remote Sony cameras, as well as any other compatible camera, using stereo cables. 2.740 firmware can be used with mono connections, such as a button trigger or foot pedal, as well as stereo remote camera cables. 2.740 and 2.840 can be used together.

New Feature:

- Long Range Receive Mode: Rx LR mode has been added to the Plus IIIe menu. It is designed to be used on the radio connected to a remote camera. It provides a longer contact time for the remote camera, for more consistent triggering with continuous shooting modes. Use LR mode for the transmitting radio and Rx LR for remote radios.